



■Taping Specification



Symbol		A	B	Do	D1	E	F
DIMENSION	3. 2*2. 5	2. 8	3. 5	1. 5	1	1. 75	3. 5
Symbol		K	Po	P1	P2	T	W
DIMENSION	3. 2*2. 5	1	4	8	2	0. 25	8

Unit:mm



Symbol		H	F	G	W	T	X	Y
Dimension	3.2*2.5	40°	21±0.8	120	17.5	2	50	250